



typ	X	B	C	D	H1	H2
DWS 100	992-1008	585	351-357	591	1970	1950
DWS 110	1092-1108	685	351-357	691	1970	1950
DWS 120	1192-1208	685	451-357	691	1970	1950
DWS 140	1392-1408	785	551-357	791	1970	1950